



SDMS Doc ID 2013713

San Martin Area Perchlorate Investigation Data as of March 20, 2003

Summary of Results as of March 20, 2003

Concentration	Number of Samples
Non-Detect (< 4 ppb)	491
4 to 9.9 ppb	273
10 to 19.9 ppb	14
20 to 39.9 ppb	2
40 to 100 ppb	2
Total	782

LEGEND

Perchlorate Results, parts per billion

- Non-Detect (< 4)**
- 4 - 9.9
- 10 - 19.9
- 20 - 39.9
- 40 - 100



★ Former Olin Corporation Facility

* The city of Morgan Hill has taken three wells temporarily off line because of perchlorate detections of 6 parts per billion, 5 ppb, and 4 ppb respectively. Two more tests showed that the first two wells were below the detection limit of 4 ppb. As a precaution, all three wells remain off line. One well is located at the corner of Dunne and Murphy, another is near a soccer complex by U.S. Highway 101, and the third is close to US 101 and Dunne. For information about its municipal water, the Morgan Hill Public Works Department can be reached at (408) 776-7337.

** Perchlorate not detected above 4 parts per billion. Perchlorate may be present at concentrations less than 4 parts per billion. The California Dept. of Health Services advisory Action Level is 4 parts per billion. Map prepared by Santa Clara Valley Water District www.valleywater.org 1-888-HEY-NOAH (1-888-439-6624) See website for more information

5000 0 5000 10000 Feet

